Oil-free bushings, washers Cul-tree bushings, washers Lubrication-free bushings/gaskets are bearing components that do not require lubrication. Since bearings are usually subjected to a lot of frictional resistance that generates heat, lubricants such as oil or grease are used to prevent seizure or abnormal wear that may result from this frictional heat. Non-lubricated bushings do not require lubrication because the bearing body has a lubrication structure that is achieved by a lubricant or embedded solid lubricant or similar in the bearing body. Non-lubricated washers are washers that can accept thrust loads and have the same lubrication structure as non-lubricated bushings. Both lubrication-free bushings and washers are very effective in situations where the use of lubricant is difficult due to the operating environment or structure. They also greatly reduce maintenance costs by eliminating the need for periodic lubrication and provide long-term stable operation.

JDB-JTW-13	13.2	н	н	"	"	"	н
JDB-JTW-14	14.2	п	"	u.	u.	"	"
JDB-JTW-15	15.2	50	"	35	"	"	"
JDB-JTW-16	16.2	н	u	"	"		"
JDB-JTW-18	18.2	II	"	"	"	"	"
JDB-JTW-20	20.2	"	5	"	M5	6	"
JDB-JTW-25	25.2	55	"	40	"	"	"
JDB-JTW-30	30.2	60	"	45	"	"	"
JDB-JTW-35	35.2	70	"	50	M6	7	"
JDB-JTW-40	40.2	80	7	60	"	11	"
JDB-JTW-45	45.3	90		70	"	"	"
JDB-JTW-50	50.3	100	8	75	"	11	4
JDB-JTW-55	55.3	110	"	85	"	"	"
JDB-JTW-60	60.3	120	"	90	M8	9	"
JDB-JTW-65	65.3	125	"	95	"	"	"
JDB-JTW-70	70.3	130	10	100	n	n	"
JDB-JTW-75	75.3	140	"	110	"	"	"
JDB-JTW-80	80.3	150	"	120	"	"	"
JDB-JTW-90	90.5	170	"	140	M10	11	"
JDB-JTW-100	100.5	190	"	160		n	"
JDB-JTW-120	120.5	200	"	175	"	"	н

单位Unit: mm<sup>2</sup>

孔数

2

...

Size



运动方向 Sliding direction

φd

10.2

12.2

φD

30

40

型号规格 Standard No.

JDB-JTW-10

JDB-JTW-12





 $\phi d_1$ 

3.5

...

螺孔 Bolt Hole

M3

...

平头螺钉 Crop Bolt

 $\phi D_1$ 

20

28

...

3

...

SELF-LUBRICATING BEARING Thrust Washer / Lubrication-Free Copper Alloy Washer (Part Nurr yhrust Washer / Lubrication-Free Copper Alloy Washer